

Digital Altimeter with Compass WS110

Features:

- 1) Altimeter(m,feet)
- 2) Barometric pressure (hPa,inHg,mmHg)
- 3) Temperature (°C/°F)
- 4) Digital compass
- 5) Perpetual calendar
- 6) Low battery indicator
- 7) Neck band included for easy carrying

Specifications:

- 1) Compass range: 0°to 359°(digital) 1 to 32 pointers (graphical)
- 2) Height accuracy: +/-0.5m
- 3) Temperature range: -20°C to +60°C (-4°F to 140°F)
- 4) Temperature resolution: 0.1°C/0.2°F
- 5) Temperature accuracy: +/-1.0°C
- 6) Pressure resolution: 0.1hPa(0.1mmHg, 0.01inHg)